



## IMPERMEABLE BAG – WASHING RECOMMENDATIONS

### ***DO NOT OVERDRY:***

Dry for approximately 10 minutes. Excessive drying temperature will cause damage and delimitation of the bag fabric.

Set drying temperature at 60C (max 70C).

Allow cool down of at least 8-10 minutes after drying cycle. Remove from the dryer as soon as cool down is complete and fold or store flat.

Bags may also hang dry.

### ***DO NOT OVERBLEACH***

Too much bleach may cause premature degradation and deterioration of the laminated fabric. Do not use more than 1.4l of 1% chlorine bleach per 45kg load (or proportions thereof).

Addition of ANTI-CHLOR at 1<sup>st</sup> or 2<sup>nd</sup> rinse after chlorine bleach operation will eliminate residual bleach.

Use of oxygenated bleach is recommended.

DO NOT presoak in bleach.

Bag is best washed inside out.

### ***DO NOT OVERLOAD***

Load equipment to no more than 80% of soiled weight.